



Sitting on big store

Accesses Monday (<http://www-bd.fnal.gov/cgi-mach/machlog.pl?nb=pbar08>

&action=view&page=318&load=) and Tuesday

- DRF1 is up to max now.
- Shunt work - appears to be working
- Tank motor controls
 - Mv305 - had limit switch broken
 - mh201U was sticking. Couldn't get it properly aligned. Ran fine from the box. Works, but not smooth movement.
 - Mv106d appeared to work.
- Rad survey
 - 10 is a lot quieter than before shutdown.
 - D-pipe next to accum inj septum is now hot. May want to bump in that region.
- Two small drippers
- Some warm quads. - uniform lack of flow in magnets.
 - Thermal images - <http://www-bd.fnal.gov/cgi-mach/machlog.pl?nb=pbar08&action=view&page=323&load=>
- Equalizers
 - Core hor. Are in. Didn't make it worse? Not clear yet that it has improved anything.
 - Bands 2 and 3 were noticeably better
 - Band 1 was a wash.
 - Emittances look the same.
 - Debuncher notch filter
 - Val claims it is 3% worse.
 - Measured notch filter response without old notch
 - we did what we wanted. When inserted new equalizer, got reflections from somewhere. 2.6nsec delay in cable...to fix the problem we need an access. Will take a long time, so

- wait until October shutdown.
 - If we increase gain in long leg of notch filter, would improve cooling.
 - Will make remote control attenuation in long leg. Increase by 24%. Should be significant improvement. Motor to control attenuator...
- 4-8GHz TWT repair
 - Repair was successful.
 - Some cable ultimately had to be removed since it was too long even with the trombone set to zero.
 - Wes and Pete turned down the helix voltage on both TWTs. The helix voltage changes the length of the TWT.
 - So when phased the system, phased the second leg to the first leg.
 - Overall delay was 42psec too long, which was blowing the beam up.
- A:LQ trip (<http://www-bd.fnal.gov/cgi-mach/machlog.pl?nb=pbar08&action=view&page=325&load=>)
 - DC overcurrent trip, but that is shorted out.
 - Thought there was a problem with the interlock box.
 - Ran for a while, had another trip.
 - In series with DC Overcurrent is also an AC overcurrent.
 - The last trip, the current went to zero, but the PS stayed on.
 - Opened the PS, breaker tripped. One cable was very movable since the cable sheered.
- Debuncher beam valve controls.
 - Bv610
- Moved target to middle disk.
- ISEP trip
 - <http://deb-nmr-scope.fnal.gov:8001/>
 - Once the scope is triggered and you have copied the trace image, go to the "data" tab and in the Talk/Listen area enter the command
 - **fpanel:press singleseq**
 - and hit the Send button. Go
 - Go back to the home page, wait for the screen to refresh and verify that the display is cleared and the scope is waiting for the next trigger.
- 4 day shutdown
 - Big job is to support Japanese target station experiment.
 - Clean up work list items.